TRICO EQUIPMENT AND SERVICE SPECIFICATIONS

Hudson

1929 OPEN GREATER HUDSON TYPE 3A

PART NAME	PART NUMBER	SERVICE NUMBER
BLADE	P-850-6½"C	U-778-6½"L
DRIVER (LEFT SIDE) ARM PASS. (RIGHT SIDE)	1898-5¼"C	P-2164-5¼"E
DRIVER (LEFT SIDE) MOTOR PASS. (RIGHT SIDE)	RSB-40	KSB-163
HOSE	846	

ATTACHMENT PARTS

Holding Nut	1418-C	Handle	810-C
Mounting Clip	145-C	Knob	75225-11C

MOTOR REPAIR PARTS

Repair Kit	SP. 1060
Shaft	S-488-38C
Cam	491-J

1929 CLOSED COUPE, COACH, SEDAN TYPE 1A SPECIAL

PART NAME	PART NUMBER	SERVICE NUMBER
BLADE	P-850-8¼"E	U-778-8¼"L
DRIVER (LEFT SIDE) ARM PASS. (RIGHT SIDE)	1898-8¼"E	P-2164-8¼"E
DRIVER (LEFT SIDE) MOTOR PASS. (RIGHT SIDE)	RSL-50	RSL-218
HOSE	846	

ATTACHMENT PARTS

Knob	1134-D

MOTOR REPAIR PARTS

Repair Kit	SP. 1063
Shaft	489-5D
Cam	479-1J

1929 CLOSED LANDAU, VICTORIA, CLUB SEDAN, 7 P.SEDAN TYPE 3A

PART NAME	PART NUMBER	SERVICE NUMBER
BLADE	P-850-7¼"A	U-778-7¼"L
DRIVER (LEFT SIDE) ARM PASS. (RIGHT SIDE)	1898-6½"A	P-2164-6½"E
DRIVER (LEFT SIDE) MOTOR PASS. (RIGHT SIDE)	S-30	
HOSE	846	

ATTACHMENT PARTS

Knob	75225-G

MOTOR REPAIR PARTS

Repair Kit	SP. 1071
Shaft	1933-17A
Cam	

1928 CLOSED

PART NAME	PART NUMBER	SERVICE NUMBER
BLADE	850-8"E	U-778-8¼"L
DRIVER (LEFT SIDE) ARM PASS. (RIGHT SIDE)	1898-6¼"E	P-2164-6¼"E
DRIVER (LEFT SIDE) MOTOR PASS. (RIGHT SIDE)	S-52	
HOSE	846	

ATTACHMENT PARTS

MOTOR REPAIR PARTS

Repair Kit	Sp. 1071
Kicker	1113-J

PART NAME	PART NUMBER	SERVICE NUMBER
BLADE		
DRIVER (LEFT SIDE) ARM PASS. (RIGHT SIDE)		
DRIVER (LEFT SIDE) MOTOR PASS. (RIGHT SIDE)		
HOSE		

PART NAME	PART NUMBER	SERVICE NUMBER
BLADE		
DRIVER (LEFT SIDE) ARM PASS. (RIGHT SIDE)		
DRIVER (LEFT SIDE) MOTOR PASS. (RIGHT SIDE)		
HOSE		

Printed in U.S.A.